DOCKET NO.: 295484US41X PCT/aj

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

IN RE APPLICATION OF: Arnaud PREMARTIN, et al.

PATENT NO.: 8,011,543 GROUP: 3782

ISSUED: September 6, 2011 EXAMINER: ELKINS, GARY E

FOR: LOAD CARRIER MOUNTED AT THE REAR OF A MOTOR VEHICLE

REQUEST FOR CERTIFICATE OF CORRECTION

DIRECTOR OF THE UNITED STATES PATENT AND TRADEMARK OFFICE ALEXANDRIA, VA 22313-1450

SIR:

The following is a Request for Certificate of Correction in Serial Number 10/591,497, now U.S. Patent Number 8,011,543.

In accordance with the provisions of Rule 322 of the Rules of Practice, which implement 35 USC 254, the U.S. Patent and Trademark Office is respectfully requested to issue a Certificate of Correction in the above-identified patent.

In light of the fact that the errors were the fault of the U.S. Patent and Trademark Office, no fees are required. The requested corrections are listed on FORM P.T.O. 1050.

Respectfully submitted,

OBLON, SPIVAK, McCLELLAND, MAIER & NEUSTADT, L.L.P.

Re

Philippe J.C. Signore, Ph.D.

Registration No. 43,922

Varoes D. Hamilton Registration No. 28,421

Customer Number

22850

Tel. (703) 413-3000 Fax. (703) 413-2220 (OSMMN 07/09) UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.:

8,011,543

DATED:

September 6, 2011

INVENTOR(S):

Arnaud PREMARTIN, et al.

It is certified that an error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

On the title page, Item (87), the PCT Pub. No. is incorrect. Item (87) should read:

-- (87) PCT Pub. No.: **WO2005/085006** PCT Pub. Date: **Sep. 15, 2005** --

Mailing address of sender:

Patent No.

8,011,543

OBLON, SPIVAK MCCLELLAND, MAIER & NEUSTADT, L.L.P. 1940 DUKE STREET ALEXANDRIA, VIRGINIA 22314 Tel. (703) 413-3000

Tel. (703) 413-3000 Fax. (703) 413-2220 (OSMMN 07/09) No. of add'l copies @ .30 per page

